



10/600,568

GJC

PATENT
Customer No. 22,852
Attorney Docket No. 4329.2444-01

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,897,143 B2)
)
Inventors: HIROSHI TOYODA ET AL.)
)
Issue Date.: May 24, 2005)
)
For: METHOD OF MANUFACTURING)
SEMICONDUCTOR DEVICE)
INCLUDING TWO-STEP)
POLISHING OPERATION FOR CAP)
METAL)

**Certificate
JUN 23 2005
of Correction**

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistake identified in the appended Form occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

JUN 24 2005

Please charge any required fees not included herewith to our deposit account
06-0916.


Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: _____

6/17/05

By: _____


Richard V. Burgujian
Reg. No. 317441

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. 6,897,143 B2

DATED: May 24, 2005

INVENTORS: Toyoda et al.

It is hereby certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Claim 12, column 14, line 44, change "bonde" to --boride--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

Patent No. 6,897,143 B2

No. of additional copies
@ .30¢ per page

JUN 24 2005